

TPMS OE Sensors Application List

RDKS OE-Sensoren Verwendungsliste

(Status: 01.2022)



Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeugmarke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
Alfa Romeo	Giulia	05.2016		50 547 691	A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0,4 Nm
Alfa Romeo	Stelvio	12.2016		50 547 691	A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0,4 Nm
BMW	1-series (F20, F21)	03.2014	11.2019	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm
BMW	2-series (F22, F23, F45, F46)	03.2014	11.2021	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm
BMW	3-series (F30,F31,F34)	03.2014	10.2018	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm
BMW	4-series (F32, F33, F36)	03.2014	06.2021	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm
BMW	i3 (I01)	08.2013		36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm
BMW	i8 (I12)	03.2014		36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0,4 Nm

Car Brand	Model	from year onwards	by month/year		OE Number of Sensor	Marking on Sensor	Order Number Replacement	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr		OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
BMW	M2 (F87)	11.2015			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	M3 (F80)	04.2014			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	M4 (F82, F83)	04.2014			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	X1 (F48)	07.2015			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	X2 (F39)	11.2017			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	X5 (F15, F85)	05.2013			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
BMW	X6 (F16, F86)	08.2014			36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
Chrysler	C200	03.2014	12.2016	4), 5)	53 394 085	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Chrysler	Pacifica	03.2016		4), 5)	53 394 085	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Citroen	C4 Aircross	04.2014	04.2017		1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Citroen	C-Zero	10.2014		from Org.-Nr: 13749	1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Dodge	Durango	10.2010		4), 5)	53 394 085	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Dodge	Dart	10.2016		4), 5)	53 394 085	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Fiat	124 Spider	03.2016		3) LL3 + LAB	BHB6-37140	A2C11324100, A2C11324101	A2C1132410180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Ford	Galaxy (WA6)	05.2006	04.2015		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Ford	S-Max (WA6)	05.2006	04.2015		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Ford	Mondeo IV (BA7)	03.2007	12.2014		8G92 1A189-KB	S180052020	S180084730Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Honda	Accord	07.2013			42753-TL0-G520	S180052059	S180052059Z	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm
Honda	Jazz	11.2014	12.2015		42753-TL0-G520	S180052059	S180052059Z	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	Accent/Solaris (RB)	08.2014	04.2017	7)	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Accent/Solaris (YC)	04.2017		7)	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Elantra (AD)	01.2016			52933-F2000	A2C98607702	A2C9860770280	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Genesis (DH)	01.2014			52933 2J100	A2C99537900	A2C9953790080	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Grand Santa Fe (NC)	05.2013	03.2018		52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Grandeur (HG, IG)	03.2014			52933 D4100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	H-1 (TQ)	12.2014			52933-4H100, 52940-4F100	S180052072	2910000196000	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	IONIQ Hybrid	06.2016			52933 D4100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	i20 (PB/PBT)	08.2008	06.2014		52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	i20 MY 2012 (PB)	06.2014	EOP		52933 2M650	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	iX20 (JC)	11.2010	05.2013		52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Hyundai	iX20 (JC)	05.2013			52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	i30 (GD)	11.2011	12.2016		52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	i30 (PDE)	12.2016	07.2018	7)	52933-F2000	A2C98607702	A2C9860770280	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	i30N (PDE)	08.2017			52933-F2000	A2C98607702	A2C9860770280	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Kona (OS)	09.2017			52933-F2000	A2C98607702	A2C9860770280	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Hyundai	Santa Fe (DM)	08.2012	08.2018		52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Infiniti	Q50	04.2013			407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Infiniti	Q60	10.2013			407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm

Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
Infiniti	QX60	09.2013		407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Jaguar	X-Type (X400)	01.2007	12.2009	C2Z31510	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	I-Pace (EV400)	05.2018		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	F-Type (X152)	10.2012		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	F-Pace (X761)	12.2015		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	E-Pace	09.2017		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XE (X760)	02.2015		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XF (X250)	03.2008	06.2015	C2Z31510	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XF (X260)	06.2015		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XJ (X350)	05.2003	09.2009	C2Z31510	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XJ (X351)	10.2009		C2D47173	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	XK (X150)	03.2006	07.2014	C2Z31510	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jaguar	S-Type	04.2002	08.2007	C2Z31510	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Jeep	Renegade	12.2014	4), 5)	53305555	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Jeep	Compass (MK50)	12.2016	4), 5)	53 394 085	A2C99154501	A2C9915450180	2910000063400	-	TG1D	-	0.4 Nm
Jeep	Grand Cherokee (WK2 - MY2017)	04.2016		50 547 691	A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Carens (UN)	12.2006	02.2013	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Carens (RP/RP PE)	03.2013		52933 2J100	A2C99537900	A2C9953790080	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Cee'd (JD)	03.2012	06.2018	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Niro	04.2016		52933 D4100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Optima Hybrid	03.2012	08.2013	52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Optima (TF)	08.2013	06.2015	52933 2M650	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Optima Hybrid (TFe)	03.2014	06.2015	52933 2M650	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Optima (JF)	08.2015		52933 D4100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Picanto (TA)	04.2014	11.2016	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Rio (YB)	01.2017	3)	52933 2J100	A2C99537900	A2C9953790080	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Sorento	11.2009	09.2012	52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Sorento (XM)	07.2012	09.2017	52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Sorento (UM)	10.2014		52933 2J100	A2C99537900	A2C9953790080	2910000307500	A2C59517073	TG1C	8 Nm	0.4 Nm
Kia	Soul (AM)	02.2009	12.2013	52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Soul (SK3)	02.2018		52933 D4100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Sportage (QL)	10.2015		52933 D9100	A2C98607301	2910000102400	A2C59507828	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Venga (YN)	02.2010	04.2014	52933 1J000	S180052012	S180084710Z	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Kia	Venga (YN)	04.2014		52933 3N100, 52933 B1100	A2C14467700	A2C1446770080	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Lada	Granta	04.2015	06.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Lada	Granta	07.2016	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Lada	Kalina	10.2016	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Lada	Vesta	11.2015		407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Land Rover	Discovery 3 (L319)	07.2004	09.2009	LR086928	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm
Land Rover	Discovery 4 (L319)	09.2009	03.2017	LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm

Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core	
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz	
Land Rover	Discovery 5 (L462)	04.2017		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Discovery Sport (L550)	10.2014		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	FreeLander (L359)	10.2006		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover (L322)	2005	08.2009	LR086928	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover (L322, L405)	09.2009		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover Evoque (L538)	09.2011		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover Sport (L320)	2005	04.2010	LR086928	S180052080	S180052080Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover Sport (L320, L494)	05.2010		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Land Rover	Range Rover Velar (LY)	09.2017		LR070840	S180052076, S180052076B, A2C93315301	S180052076Z	S180084520A	A2C59517073	TG1C	8 Nm	0.4 Nm	
Maserati	Ghibli (M157)	10.2018			A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm	
Maserati	Levante (139)	10.2018			A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm	
Maserati	Quattroporte (M156)	10.2018			A2C97145802	A2C9714580280	A2C59507829	A2C59517072	TG1C	8 Nm	0.4 Nm	
Mazda	2 (DE)	10.2008	06.2015	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	3 (BL)	06.2009	03.2013	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	3 (BP)	08.2018			BDEL-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	5 (CW)	09.2010	09.2015	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	6 (GH)	08.2007	07.2013	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	6 (GJ/GL)	06.2017		3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	CX-30 (DM)	04.2019			BDEL-37140 BDMC-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	CX-5 (KE)	11.2011	05.2017	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	CX-5 (KF)	06.2017		3)	BHB6-37140 BDMC-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	CX-7 (ER)	06.2009	12.2012	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	CX-9 (TB)	08.2010	12.2015	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	MX5 (NC)	03.2010	12.2014	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	MX5 (ND)	04.2015		3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	MX5 (NC)	03.2010	12.2014	3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mazda	MX5 (ND)	04.2015		3)	BHB6-37140	A2C19397601, A2C19397602	A2C1939760180	A2C59507828	A2C59517073	TG1C	8 Nm	0.4 Nm
Mercedes Benz	Citan / T-Class (W420)	10.2021			A 420 401 2400	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
MINI	Cooper (F55, F56)	3.2014		6)	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
MINI	One (F55, F56)	3.2014		6)	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
MINI	Clubman (F54)	07.2015		6)	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
MINI	Cabrio (F57)	03.2016		6)	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm
MINI	Countryman (F60)	07.2015		6)	36 10 6 881 890	A2C97432500, A2C97432501, A2C97432502	A2C9743250080	2910000301700	A2C59517073	TG1C EVO	8 Nm	0.4 Nm

Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
Mitsubishi	ASX (ZC)	08.2014		4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Mitsubishi	i-Miev (TQ)	07.2014		4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Mitsubishi	Lancer (GS41)	08.2014		4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Mitsubishi	L200/Triton (CR)	08.2014	4), 5)	4250F1871	A2C37819407	A2C3781940780	2910000063400	-	TG1D	-	0.4 Nm
Mitsubishi	Outlander (RE)	07.2014		4250C477	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Mitsubishi	Pajero (BK)	07.2014	4), 5)	4250C275	A2C37819407	A2C3781940780	2910000063400	-	TG1D	-	0.4 Nm
Mitsubishi	Pajero Sport (QE)	01.2016	4), 5)	4250C275	A2C37819407	A2C3781940780	2910000063400	-	TG1D	-	0.4 Nm
Mitsubishi	Spacestar (EL)	07.2014	4), 5)	4250C275	A2C37819407	A2C3781940780	2910000063400	-	TG1D	-	0.4 Nm
Mitsubishi	Eclipse Cross	01.2018	4), 5)	4250C275	A2C37819407	A2C3781940780	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Altima (L33)	03.2014		407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Micra (K14)	12.2016	4), 5)	407004CB0B	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Murrano (Z51)	10.2014		407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Note (E12)	08.2013		407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	e-NV200	05.2014	09.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	e-NV200	10.2016	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Pathfinder (R51, R52)	06.2013		407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Pulsar (C13)	10.2014	09.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Pulsar (C13)	10.2016	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Qashqai (J11)	12.2013	09.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Qashqai (J11)	10.2016	08.2021	4), 5)	407004CB0A	A2C99668703, A2C99668705	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Tiida (C12)	10.2014	09.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Tiida (C12)	10.2016	07.2020	4), 5)	407004CB0A	A2C99668703, A2C99668705	2910000063400	-	TG1D	-	0.4 Nm
Nissan	X-Trail (T32)	11.2013	09.2016	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	X-Trail (T32)	10.2016	04.2020	4), 5)	407004CB0A	A2C99668703, A2C99668705	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Teana (J33)	09.2013		407003JA0B	S180052036	S180052036Z	A2C59507830	A2C59517072	TG1C	8 Nm	0.4 Nm
Nissan	Leaf (Gen2)	01.2018	4), 5)	407004CB0B	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Juke II	09.2019	4), 5)	407004CB0B	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Nissan	Juke III (F16E)	01.2022		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Nissan	Ariya	03.2022		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Nissan	Qashqai (J12)	09.2021		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Nissan	X-Trail	05.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Nissan	Tiida	08.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Nissan	Townstar	10.2021		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Peugeot	4008	11.2014		1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Peugeot	ION	10.2014	from Org-Nr: 13749	1612477080	S180052094	S180052094Z	A2C59507087	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Espace V	06.2015	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Fluence	02.2010		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Kadjar	06.2015	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Koleos	12.2013	03.2015	407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Koleos II	08.2016		407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Alpine (A110)	01.2018		407003VU0B	A2C82208303, A2C82208304	A2C8220830480	A2C59506227	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Laguna III	10.2007		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm

Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
Renault	Latitude	02.2011		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Megane III	11.2008		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Megane IV	11.2015	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Scenic III	02.2009		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Scenic IV	09.2016	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Spider	03.2010		40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Talisman	06.2015	4), 5)	407004CB0A	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Zoe	09.2012	08.2019	40 70 004 35 R	S180052064	S180052064Z	S180084500A	A2C59517072	TG1C	8 Nm	0.4 Nm
Renault	Zoe II	09.2019	4), 5)	40700 4CB0B	A2C99668703, A2C99668705	A2C9966870380	2910000063400	-	TG1D	-	0.4 Nm
Renault	Kadjar Gen 2	02.2021		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Megane IV Facelift	10.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Megane e-Tech	10.2021		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Espace Gen2	10.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Talisman ph2	07.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Kangoo Gen 3	09.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Trafic Gen 2	10.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Renault	Dokker Gen2	04.2020		407006UA0A	A2C19969003	2802003001180	2910000439900	-	TG1D Evo	-	-
Suzuki	Across	10.2020		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Alto	06.2014	12.2017	43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Cultus	09.2014	09.2020	43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Grand Vitara	06.2014	01.2019	43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Ignis	01.2017		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Jimny(Gen3)	05.2018		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Jimny	11.2014	04.2018	43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Swift	04.2014	04.2017	43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Swift (RZ/AZ)	05.2017		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Swift Sport (RZ/AZ)	06.2018		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Baleno II	06.2016		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	SX-4	06.2014		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	SX-4 S-Cross	08.2013		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Suzuki	Vitara	02.2015		43139-61M00, 43130-52S01	S180052024	S180052024Z	S180084510A	A2C59517072	TG1C	8 Nm	0.4 Nm
Tesla	Model S MY 2015	09.2014	06.2021	1034602-00-C	A2C10261600	A2C1026160080	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Tesla	Model S MY 2015	09.2014	06.2021	Black valve stem 1074812-00-B	A2C10262100	A2C1026210080	2910000418500	2910000418100	TG1C	8 Nm	0.4 Nm
Tesla	Model X	09.2015	06.2021	1034602-00-C	A2C10261600	A2C1026160080	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Tesla	Model X	09.2015	06.2021	Black valve stem 1074812-00-B	A2C10262100	A2C1026210080	2910000418500	2910000418100	TG1C	8 Nm	0.4 Nm
Tesla	Model 3	07.2018	10.2020	1034602-00-C	A2C10261600	A2C1026160080	A2C59507831	A2C59517072	TG1C	8 Nm	0.4 Nm
Tesla	Model 3	07.2018	10.2020	Black valve stem 1074812-00-B	A2C10262100	A2C1026210080	2910000418500	2910000418100	TG1C	8 Nm	0.4 Nm
Volvo	C30	10.2006	3)	31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	C30 Electric	12.2010	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	C70	03.2006	3)	31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	S40	01.2004	3)	31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	S60	01.2011	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm

Car Brand	Model	from year onwards	by month/year	OE Number of Sensor	Marking on Sensor	Order Number Replacement Sensor	Order Number Service-Kit	Order Number Valve Stem only	Generation	Torque for nut	Torque for valve core
Fahrzeug-marke	Modell (Baureihe)	ab Monat/Jahr	bis Monat/Jahr	OE Nummer Sensor	Kennzeichnung Sensor	Bestellnummer Aftermarket Sensor	Bestellnummer Service-Kit	Bestellnummer Ventilstamm	Generation	Drehmoment für Überwurfmutter	Drehmoment für Ventileinsatz
Volvo	S80L	03.2006	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	S80	03.2006	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	V50	04.2004	3)	31302096	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	V60	09.2010	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	V70	03.2006	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	XC60	05.2008	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm
Volvo	XC70	02.2007	3)	31341893	S180052050	S180052050Z	S180084520A	A2C59517072	TG1C	8 Nm	0.4 Nm

- 1) If a service kit for a sensor of type TG1B is needed for the Ford, Jaguar, Land Rover, Mazda or Volvo brand, use article number S180014561A.
- 2) If a service kit for a sensor of type TG1B is needed for the Hyundai brand, use article number S180014531A.
- 3) These vehicle models are only be equipped with direct tire pressure monitoring systems as option.
- 4) Max. designed speed of TG1D sensors: 200 km/h. Vehicle models with a maximum speed of more than 200 kph have to use a TG1C sensor instead.
- 5) Installation of sensors only in specifically approved OE and spare part rims.
- 6) Sensor also for John Cooper Works variants.
- 7) This vehicle is equipped with a indirect system in the EU. Import cars can still be equipped with a direct TPMS.

- 1) Sollte bei den Marken Ford, Jaguar, Landrover, Mazda oder Volvo ein Service-Kit für einen Sensor der Bauform TG1B benötigt werden, dann Artikelnummer S180014561A.
- 2) Sollte bei der Marke Hyundai ein Service-Kit für einen Sensor der Bauform TG1B benötigt werden, dann Artikelnummer S180014531A.
- 3) Diese Fahrzeuge sind ggfs. nur optional mit direktem Reifendruckkontrollsystem ausgestattet.
- 4) Bauartbedingte Höchstgeschwindigkeit für TG1D-Sensoren: 200 km/h. Fahrzeug-Motorisierungen mit einer zulässigen Höchstgeschwindigkeit von mehr als 200 km/h müssen alternativ einen TG1C Sensor verwenden.
- 5) Verbau von Sensoren nur in spezifisch freigegebenen OE und Ersatzteil-Felgen.
- 6) Sensor auch für John Cooper Works Varianten
- 7) Dieses Fahrzeug wird mit einem indirektem System ausgeliefert. Importfahrzeuge können noch mit direktem RDKS ausgeliefert werden.